





The plate has a "Z" fold on both sides for simplified splicing of ZMesh heating element. The ZMesh slides into each Z fold, is gently crimped or compressed, and then soldered as usual. Always keep the flame of the soldering torch on the "Z" fold and never on the ZMesh.

